

Measurements

Reference

R

Fraction / Decimal / Drill Size			Fraction / Decimal / Drill Size			Fraction / Decimal / Drill Size		
	.0135	80		.1200	31		.3160	O
	.0145	79		.1285	30		.3230	P
1/64	.0156		1/8	.1250		21/64	.3281	
	.0160	78		.1360	29		.3320	Q
	.0180	77		.1405	28		.3390	R
	.0200	76	9/64	.1406		11/32	.3438	
	.0210	75		.1440	27		.3480	S
	.0255	74		.1470	26		.3580	T
	.0240	73		.1495	25	23/64	.3594	
	.0250	72		.1520	24		.3680	U
	.0260	71		.1540	23	3/8	.3750	
	.0280	70	5/32	.1562			.3770	V
	.0292	69		.1570	22		.3860	W
	.0310	68		.1590	21	25/64	.3906	
1/32	.0312			.1610	20		.3970	X
	.0320	67		.1660	19		.4040	Y
	.0330	66		.1695	18	13/32	.4062	
	.0350	65	11/64	.1719			.4130	Z
	.0360	64		.1730	17		.4219	
	.0370	63		.1770	16	7/16	.4375	
	.0380	62		.1800	15	29/64	.4531	
	.0390	61		.1820	14	15/32	.4688	
	.0400	60		.1850	13	31/64	.4844	
	.0410	59	3/16	.1875		1/2	.5000	
	.0420	58		.1890	12	33/64	.5156	
	.0430	57		.1910	11	17/32	.5312	
	.0465	56		.1935	10	35/64	.5469	
3/64	.0469			.1960	9	9/16	.5625	
	.0520	55		.1990	8	37/64	.5781	
	.0550	54		.2010	7	19/32	.5938	
	.0595	53	13/64	.2031		39/64	.6094	
1/16	.0625			.2040	6	5/8	.6250	
	.0635	52		.2055	5	41/64	.6406	
	.0670	51		.2090	4	21/32	.6562	
	.0700	50		.2130	3	43/64	.6719	
	.0730	49	7/32	.2188	2	11/16	.6875	
	.0760	48		.2280	1	45/64	.7031	
5/64	.0781			.2340	A	23/32	.7188	
	.0785	47	15/64	.2344		47/64	.7344	
	.0810	46		.2380	B	3/4	.7500	
	.0820	45		.2420	C	49/64	.7656	
	.0860	44		.2460	D	25/32	.7812	
	.0890	43	1/4	.2500	E	51/64	.7969	
	.0935	42		.2570	F	13/16	.8125	
3/32	.0938			.2610	G	53/64	.8281	
	.0960	41	17/64	.2656		27/32	.8438	
	.0980	40		.2660	H	55/64	.8594	
	.0995	39		.2720	I	7/8	.8750	
	.1015	38		.2770	J	57/64	.8906	
	.1040	37		.2810	K	29/32	.9062	
	.1065	36	9/32	.2812		59/64	.9219	
7/64	.1094			.2900	L	15/16	.9375	
	.1100	35		.2950	M	61/64	.9531	
	.1110	34	19/64	.2969		31/32	.9688	
	.1130	33		.3020	N	63/64	.9844	
	.1160	32	5/16	.3125		1	1.0000	

